

SunCoke Energy, Inc.  
Form 8-K  
November 23, 2011

**UNITED STATES**  
**SECURITIES AND EXCHANGE COMMISSION**

Washington, D.C. 20549

**FORM 8-K**

**CURRENT REPORT**

**PURSUANT TO SECTION 13 OR 15(d) OF THE**

**SECURITIES EXCHANGE ACT OF 1934**

**Date of Report (Date of earliest event reported): November 18, 2011**

**SUNCOKE ENERGY, INC.**

(Exact name of registrant as specified in its charter)

**Delaware**  
(State or other jurisdiction

of incorporation)

**001-35423**  
(Commission

File Number)

**90-0604593**  
(IRS Employer

Identification No.)

Edgar Filing: SunCoke Energy, Inc. - Form 8-K

**1011 Warrenville Road, Suite 600**

**Lisle, Illinois**  
(Address of principal executive offices)

**Registrant's telephone number, including area code: (630) 824-1000**

**60532**  
(Zip Code)

N/A

(Former name or former address, if changed since last report.)

Check the appropriate box below if the Form 8-K filing is intended to simultaneously satisfy the filing obligation of the registrant under any of the following provisions (see General Instruction A.2. below):

- ..  Written communications pursuant to Rule 425 under the Securities Act (17 CFR 230.425)
- ..  Soliciting material pursuant to Rule 14a-12 under the Exchange Act (17 CFR 240.14a-12)
- ..  Pre-commencement communications pursuant to Rule 14d-2(b) under the Exchange Act (17 CFR 240.14d-2(b))
- ..  Pre-commencement communications pursuant to Rule 13e-4(c) under the Exchange Act (17 CFR 240.13e-4(c))

**Item 8.01 Other Events.**

Section 1503 of the Dodd-Frank Wall Street and Consumer Protection Act requires disclosure in a Current Report on Form 8-K of the receipt of an imminent danger order issued by the Mine Safety and Health Administration pursuant to section 107(a) of the Federal Mine Safety and Health Act of 1977 (the Mine Act ).

On November 18, 2011, Dominion Coal Corporation, a subsidiary of SunCoke Energy, Inc., received an imminent danger order under section 107(a) of the Mine Act at its Dominion No. 36 mine located in Buchanan County, Virginia (the Order ). The Order alleges that the roof along the belt and track entry of an intake air course is unsound and not safe for travel. No injuries occurred.

The cited area is part of previously mined land and is not in production. Immediate action was taken to cordon off the cited area to temporarily prevent entry. We are implementing corrective measures to install additional roof supports.

**SIGNATURE**

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned thereunto duly authorized.

**SUNCOKE ENERGY, INC.**

By: /s/ Michael J. Thomson  
Michael J. Thomson

President and Chief Operating Officer

Date: November 23, 2011